

	TRAFFIC CRASH REPORT	LOCAL REPORT NUMBER		TI I COLLEGE
1			1 0 2 8 0 0 5 3 4 1 3 2	NJURY 2 - UNSOLVED
1	OH-2 OH-1P STARE REPORTABLE DOLLAR AMOUNT PROPERTY DOLLAR AMOUNT DOLLAR		t [0 ₁ 2] UNIYS	98 - ANIMAI
	18.3. UVILLAGE. Clearcrook			
SOURCE TO SECURITION OF THE ACCOUNT	LATITUDE LONGITUDE	// O LATITUDE		181318191
STATE TOTAL CONTINUES CO	□ DIVIDED N- NORTHBOUND E- EASTBOUND S- SOUTHBOUND W- WESTBOUND N- NORTHBOUND W- WESTBOUND N- NORTHBOUND W- WESTBOUND	D TYPES OR MILEPOST 2 ALLEY CR - CIRCLE AVENUE CT - COURT	HE - HEIGHTS MP - MILEPOST PL - PLACE ST - SI HW - HIGHWAY PK - PARKWAY RD - ROAD TE - TE	RRACE
DESCRIPTION	S R LOCATION ROUTE NUMBER LOC PREFIX LOCATION ROAD NAME N. S.		ROAD ROUTE TYPES 1 IR-INTERSTATE ROUTE (INC. TURNPIKE) CR TYPE 2 US-US ROUTE TR	- NUMBERED COUNTY ROUTE
Transport Control Co	☐ MILES N, S, O REFERENCE HOUSE	N, S.		ROAD
STATE STAT	REFERENCE POINT USED	11 - RAILWAY GRADE CROSSING 12 - SHARED-USE PATHS OR TRAILS	INTERSECTION RELATED 1 - ON ROADWAY 2 - ON SHOULDER 3 - IN MEDIAN	EVENT 5 - ON GORE 6 - OUTSIDE TRAFFICWAY
MONITORIS TRANSPORT OR AND COLUMN TO AND COLUMN TO AND CONTROL OR ADDRESS TRANSPORT OR AND COLUMN TO	1 - STRAIGHT LEVEL 4 - CURVE GRADE PRIMARY SECONDARY 02 2 - STRAIGHT GRADE 9 - UNKNOWN 03	- WET 06 - WATER (STANDIN - SNOW 07 - SLUSH	NG, MOVING) 10 - OTHER	
CONTROL MARKENS SUBSTITUTE STORE SUBSTITUTE SUB	1 × NOT COLLISION BETWEEN 2 - REAR-LEND 5 - BACKING 8 - SIDESWIPE, OPPOSITE 1WO MOTOR VEHICLES 3 - HEAD-ON 6 - ANGLE DIRECTION	1 - CLEAR 2 - CLOUDY	5 - SLEET, HAIL B. BLOWING SAND, SO	NDS
SAME AND LOCATION AND AND AND AND AND AND AND AND AND AN	2 - BLACKTOP, BITUMINOUS, STONE ASPHALT 5 - DIRT SECONDARY 1 - DAYLIG 2 - BLACKTOP, BITUMINOUS, STONE 3 - DUSK	6 - DARK - UNF 7 - GLARE*	KNOWN ROADWAY LIGHTING ZONE RELATED	YES, SCHOOL BUS DIRECTLY INVOLVED YES, SCHOOL BUS
Traffic Units 1 & 2 were eastbound on E State Route 73 and when at the 300 block, Unit 2 stopped for a vehicle turning into a driveway. Traffic Unit 1 failed to assure clear distance ahead and collided with the rear of Traffic Unit 2. The brake lights on Traffic Unit 2 were functioning properly. Provide Addition 10 Secretary Note 10 Secreta	WORK LAW ENFORCEMENT PRESENT 1 - LANE CLOSURE 4 - INTER ZONE (OFFICERWEHIG(E) 2 - LANE SHIFT/CROSSOVER 5 - OTHE RELATED LAW ENFORCEMENT PRESENT 3 - WORK ON SHOULDER OR MEDIAN	RMITTENT OR MOVING WORK	1 - BEFORE THE FIRST WORK ZONE WARNING SIGN 2 - ADVANCE WARNING AREA	
1 0 2 8 2 0 1 8 1 2 5 2 1 2 5 2 1 3 2 1 3 2 1 3 0 1 9 0 10 5 9 0 10 6 10 6 10 6 10 6 10 6 10 6 10 6	Traffic Units 1 & 2 were eastbound on E State Route 73 and when a the 300 block, Unit 2 stopped for a vehicle turning into a driveway. Traffic Unit 1 failed to assure clear distance ahead and collided with the rear of Traffic Unit 2. The brake lights on Traffic Unit 2 were functioning properly. ■ REPORT TAKEN BY ■ SUPPLEMENT (CORRECTION OR ADDITION TO AN EXISTING REPORT SENT TO ODPS)	h	73 Unit 1 Unit 2)	
OFFICER'S NAME * OFFICER'S BADGE NUMBER CHECKED BY Page 1 of 4	DATE CRASH REPORTED TIME CRASH REPORTED DISPATCH TIME			
	OFFICER'S NAME	OFFICER'S BADGE NUMBER C	CHECKED BY	+====





OHIO SAFETY MOTORIST / NON-MOTORIST / OCCUPANT L_P_1_1_8_1_0_2_18_0_0_5_3_4_1_1						
UNIT NUMBER NAME LAST, FIRST, MIDDLE Zimmerman, Caleb Michael		DATE OF BIRT	H 2 5 2 0 0 2 16 M F - FEMALE M - MALE			
ADDRESS, CITY, STATE, ZIP 8129 Woodbridge CT, Springboro, Ohio 45066 (513)783-3196						
INJURIES INJURIED TAKEN BY EMS AGENCY	1	AFETY EQUIPMENT USED DOT C				
OL STATE OPERATOR LICENSE NUMBER OLC CL	NO LUIS E	ALCOHOL TEST STATUS ALCOHOL TE				
OFFENSE CHARGED (CITATION NUMBER	HANDS-FREE DRIVER DISTRACTED BY			
UNIT NUMBER NAME LAST, FIRST, MIDDLE	August Great Biotarios	DATE OF BIRT	H AGE GENDER			
ADDRESS, CITY, STATE, ZIP CONTACT PHONE- INCLUDE AREA CODE						
729 Smiley AVE, Cincinnati, Ohio 45246	MEDICAL FACILITY INJURED TAKEN TO S/		(513)324-9907 OMPLIANT SEATING POSITION AIR BAG USAGE EJECTION TRAPPED			
OL STATE OPERATOR LICENSE NUMBER OL CIJ	ASS NO CONDITION ALCOHOL/DRUG SUSPECTED	0 4 LOHOL TEST STATUS ALCOHOL TE				
О H RN688796 4	OFFENSE DESCRIPTION	LILI 1	+ ANDS-FREE DRIVER DISTRACTED BY			
Tuning Tuning			DEVICE USED			
INJURED						
SEATING POSITION 01 - FRONT - LEFT SIDE (MOTORCYCLE DRIVER) 02 - FRONT - MIDDLE 03 - THIRD - LEFT SIDE (MOTORCYCLE SIDE CAR) 04 - FRONT - MIDDLE 05 - FRONT - MIDDLE 06 - SECOND - LEFT SIDE (MOTORCYCLE PASSENGER) 10 - SECOND - LEFT SIDE (MOTORCYCLE PASSENGER) 10 - SECOND - MIDDLE 11 - PASSENGER IN UNENCLOSED CARGO AREA 11 - NOT DEPLOYED 2 - DEPLOYED FRONT 3 - DEPLOYED FRONT 3 - DEPLOYED SIDE 4 - DEPLOYED BOTH FRONT/SIDE 5 - NON-MOTORIST 4 - DEPLOYED BOTH FRONT/SIDE 6 - SECOND - MIDDLE 11 - PASSENGER IN OTHER ENCLOSED CARGO AREA 16 - OTHER 16 - SECOND - RIGHT SIDE (NON-TRAILING UNIT SUCH AS A BUS. PICK-UP WITH CAP) 99 - DEPLOYED FRONT 99 - DINKNOWN 9 - DEPLOYED 90 - DINKNOWN						
EJECTION TRAPPED 1 - NOT EJECTED 2 - TOTALLY EJECTED 2 - EXTRICATED BY MECHANICAL MEANS 4 - NOT APPLICABLE 3 - EXTRICATED BY NON-MECHANICAL MEANS	OPERATOR LICENSE CLASS 1 - CLASS A 2 - CLASS B 3 - CLASS C 4 - REGULAR CLASS (OHIO IS "D") 5 - MCMOPED QNLY CONDITION 1 - APPARENTLY NORMAL 2 - PHYSICAL IMPAIRMENT 3 - EMOTIONAL (DEPRESSED, AN 4 - ILLNESS	6 - UNDER THE I	ALCOHOL/DRUG SUSPECTED 1 - NONE 1 - NONE 2 - YES - ALCOHOL SUSPECTED 3 - YES - HBD NOT IMPAIRED 4 - YES - DRUGS SUSPECTED 5 - YES - ALCOHOL AND DRUGS SUSPECTED			
1 - NONE GIVEN 1 - NON 2 - BLO 2 - TEST REFUSED 3 - TEST GIVEN, CONTAMINATED SAMPLE/UNUSABLE 4 - TEST GIVEN, RESULTS KNOWN 4 - BRE 5 - OTH	OOD 2 - TEST REFUSED NE 3 - TEST GIVEN, CONTAMINATED SAMPLE/UNUSABLE ATH 4 - TEST GIVEN, RESULTS KNOWN	1 - NONE 1 - NO DIS 2 - BLOOD 2 - PHONE 3 - URINE 3 - TEXTIN 4 - OTHER 4 - ELECTI 5 - OTHER	TRACTED BY TRACTION REPORTED 6 - OTHER INSIDE THE VEHICLE 7 - EXTERNAL DISTRACTION GGE-MAILING RONIC COMMUNICATION DEVICE ELECTRONIC DEVICE STION DEVICE, RADIO, DVD)			
D Balogh, Kelly Ann		0 9 1	2 3 2 0 0 2 16 F FEMALE M-MALE			
ADDRESS, CITY, STATE, ZIP 8405 Wandering Brook WAY, Waynesville, Ohio 45068 (513)783-3196						
INJURIES INJURED TAKEN BY EMS AGENCY	l l'e	0 4 DOT CC MOTORC				
UNIT NUMBER NAME LAST, FIRST, MIDDLE DATE OF BIRTH 1 2 1 1 3 1 1 9 5 6 61 F F - FEMALE M - MALE						
6936 Lighthouse PT, Maineville, Ohio 45039 contact phone-include area code (513)324-9907						
INJURIES INJURED TAKEN BY EMS AGENCY	l lr	O 4	1131131 1131 1131 1131 1			